

# Analysis & Information Online


## Federal Motor Carrier Safety Administration

### Roadside Inspection

This module provides summarized data for five fiscal or calendar years including current year to date information on all roadside inspections conducted on motor carriers that transport property or passengers in interstate or intrastate commerce.

A roadside inspection is an examination of individual commercial motor vehicles and drivers by a Motor Carrier Safety Assistance Program (MCSAP) inspector to determine if they are in compliance with the Federal Motor Carrier Safety Regulations (FMCSRs) and/or Hazardous Materials Regulations (HMRs.) Serious violations result in the issuance of driver or vehicle OOS orders. These violations must be corrected before the affected driver or vehicle can return to service.

### Summary of Roadside Inspections in New Mexico



Roadside Inspection Activity (New Mexico)	FY 2009		
	Fed	State	Total
Number of Inspections	7,066	122,335	129,401
I. Full	2,332	12,615	14,947
II. Walk-Around	1,412	35,829	37,241
III. Driver Only	3,255	72,874	76,129
IV. Special Study	0	116	116
V. Terminal	67	254	321
VI. Radioactive Materials	0	647	647
Driver OOS Rate	0.89%	6.09%	5.81%
Vehicle OOS Rate	16.35%	18.57%	18.41%
Hazmat OOS Rate	0%	1.63%	1.62%

Data Source: FMCSA Motor Carrier Management Information System (MCMIS) data snapshot as of 4/23/2010.

The data presented above are accurate as of this date, but are subject to update as new or additional information may be reported to MCMIS following the snapshot date.